
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-127	Smoke	10/21/2008	ADS/TM	S09QQ_010MH	Dry	Yes	924.48

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09QQ_017G1	S09QQ_017MH	S09QQ_016MH	154.9074	8
S09QQ_010G1	S09QQ_010MH	S09QQ_017MH	274.5761	8
S09QQ_012G1	S09QQ_012MH	S09QQ_010MH	219.1625	8
S09QQ_016G1	S09QQ_016MH	S09QQ_006MH	275.8307	8

Observations & Photos

Obs_ID S1028-127-OB01

Address 3405 Bateman Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_010MH

Comments Smoke from cleanout in front yard. 3405 Bateman Ave.



Picture \S1028-127-OB01-P01.jpg

Comments Front yard, 3405 Bateman Ave.

Obs_ID S1028-127-OB02

Address 3407 Bateman Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_010MH

Comments Smoke from cleanout in front yard. 3407 Bateman Ave.



Picture \S1028-127-OB02-P01.jpg

Comments Front of house, 3407 Bateman Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-127	Smoke	10/21/2008	ADS/TM	S09QQ_010MH	Dry	Yes	924.48

Obs_ID S1028-127-OB03

Address 3411 Bateman Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_012MH

Comments Smoke from cleanout in front yard. 3411 Bateman Ave.



Picture \S1028-127-OB03-P01.jpg

Comments Front of house, 3411 Bateman Ave.

Obs_ID S1028-127-OB05

Address 3401 Bateman Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_010MH

Comments Smoke from cleanout in front yard. 3401 Bateman Ave.



Picture \S1028-127-OB05-P01.jpg

Comments Front of house, 3401 Bateman Ave.

Obs_ID S1028-127-OB04

Address 3403 Bateman Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_010MH

Comments Smoke from cleanout in front yard. 3403 Bateman Ave.



Picture \S1028-127-OB04-P01.jpg

Comments Front of house, 3403 Bateman Ave.

Obs_ID S1028-127-OB06

Address 3311 Bateman Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_017MH

Comments Smoke from cleanout in front yard. 3311 Bateman Ave.



Picture \S1028-127-OB06-P01.jpg

Comments Front of house, 3311 Bateman Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-127	Smoke	10/21/2008	ADS/TM	S09QQ_010MH	Dry	Yes	924.48

Obs_ID S1028-127-OB07

Address 3301 Bateman Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S09QQ_006MH

Comments Smoke from cleanout in front yard. 3301 Bateman Ave.



Picture \S1028-127-OB07-P01.jpg

Comments Front of house, 3301 Bateman Ave.
